

Monitor ▶ Performance

Time Since Last Reset
0000:01:48:03

Reset Stats

Ethernet Statistics - Transmitted	
Total Traffic	1843180 Kbits
Total Packets	236984
Packet Errors	0
Packet Drops	0
Multicast / Broadcast Traffic	26182 Kbits
Broadcast Packets	33014
Multicast Packets	8770

Ethernet Statistics - Received	
Total Traffic	184959 Kbits
Total Packets	133635
Packet Errors	0
Packet Drops	0
Multicast / Broadcast Traffic	5 Kbits
Broadcast Packets	11
Multicast Packets	0

Wireless Statistics - Downlink	
Total Traffic	1869237 Kbits
Total Packets	249538
Error Drop Packets	0
Multicast / Broadcast Traffic	28124 Kbit
Broadcast Packets	32815
Multicast Packets	18679

Wireless Statistics - Uplink	
Total Traffic	187761 Kbits
Total Packets	150429
Error Drop Packets	308
Capacity Drop Packets	0
Retransmission Packets	173
Multicast / Broadcast Traffic	10 Kbits
Broadcast Packets	28
Multicast Packets	0
Link Quality (Uplink)	100 %
Link Capacity (Uplink)	100 %

System Statistics	
Session Drops	34
Device Reboots	14

Radar (DFS) Detections	0
------------------------	---

Downlink Packets Per MCS	
MCS 15 - 64-QAM 5/6	182238 (73%)
MCS 14 - 64-QAM 3/4	5792 (2.3%)
MCS 13 - 64-QAM 2/3	654 (0.3%)
MCS 12 - 16-QAM 3/4	684 (0.3%)
MCS 11 - 16-QAM 1/2	1291 (0.5%)
MCS 10 - QPSK 3/4	1516 (0.6%)
MCS 9 - QPSK 1/2	1368 (0.5%)
MCS 7 - 64-QAM 5/6	1117 (0.4%)
MCS 6 - 64-QAM 3/4	698 (0.3%)
MCS 5 - 64-QAM 2/3	571 (0.2%)
MCS 4 - 16-QAM 3/4	212 (0.1%)
MCS 3 - 16-QAM 1/2	148 (0.1%)
MCS 2 - QPSK 3/4	821 (0.3%)
MCS 1 - QPSK 1/2	52428 (21%)

Uplink Packets Per MCS	
MCS 15 - 64-QAM 5/6	138475 (92%)
MCS 14 - 64-QAM 3/4	1152 (0.8%)
MCS 13 - 64-QAM 2/3	672 (0.4%)
MCS 12 - 16-QAM 3/4	848 (0.6%)
MCS 11 - 16-QAM 1/2	1996 (1.3%)
MCS 10 - QPSK 3/4	1951 (1.3%)
MCS 9 - QPSK 1/2	1522 (1%)
MCS 7 - 64-QAM 5/6	795 (0.5%)
MCS 6 - 64-QAM 3/4	983 (0.7%)
MCS 5 - 64-QAM 2/3	73 (0%)
MCS 4 - 16-QAM 3/4	90 (0.1%)
MCS 3 - 16-QAM 1/2	88 (0.1%)
MCS 2 - QPSK 3/4	938 (0.6%)
MCS 1 - QPSK 1/2	846 (0.6%)